

Siltek™-Deactivated Guard Columns

(cat.# 10016, 10017, 10018, 10019, 10026, 10027, 10028, 10036, 10037, 10038)

- Siltek™-deactivated guard columns have a characteristic reflective dark golden coating. This coating is a result of the unique deactivation layer.
- Small variances in coating color and reflectivity do not affect the performance of the guard column.
- Although the Siltek™ surface shows excellent resistivity to samples containing acids and bases, prolonged exposure to highly caustic or corrosive solutions should be avoided (for example: KOH, NaOH, HF, or HCl).
- Each lot of Siltek™-deactivated guard columns is QA batch-tested to meet minimum standards of endrin (50ppb) and DDT (100ppb) breakdown limits.
- For more information about Siltek™ deactivation, call our technical service group at 800-356-1688 or 814-353-1300, ext. 4, and ask for the Siltek™ Deactivation Benefits Brochure (lit. cat.# 59803A).

Call Technical Service at 800-356-1688 or 814-353-1300, ext. 4 (or your local Restek representative) if you have any questions about this product or any other Restek product.



ISO 9001 #100-08 [001]
Rev. date: 4/29/02

Restek USA: 110 Benner Circle, Bellefonte, PA 16823
phone: (800) 356-1688 or (814) 353-1300 • fax: (814) 353-1309; www.restekcorp.com
Restek GmbH: phone: (49) 06172 2797 0 • email: RESTEK-GMBH@t-online.de
Restek France: phone: (33) 01 60 78 32 10 • email: restekfr@club-internet.fr
Thames Restek UK Ltd.: phone: (44) 01753 624111 • email: Sales@Thamesrestek.co.uk
Restek Ireland: phone: (44)2 890 814 576 • email: restekeurope@aol.com